

Image Lock™ Resin Ribbon

Premium resin ribbon providing excellent edge definition combined with exceptional abrasion and solvent resistance

A premium resin ribbon that offers exceptional abrasion and solvent resistance on a wide variety of substrates, while still providing excellent edge definition. This ribbon is an excellent choice for printing extremely dense barcodes and high-resolution graphics. Its unique resin base provides excellent resistance to outdoor elements and chemical solvents.



Suggested Applications

- High temperature, harsh environments requiring excellent print quality, print durability and label performance
- · Replacement for laminated labels
- Labeling applications requiring extreme resistance to chemicals
- · Laboratory slide label applicationsChemical drum labeling applications

Specifications

requirements of specific end-use applications.

| Attributes | | |
|--|---|--|
| Color | Black | |
| Ink Formulation | Resin | |
| Base Film | Polyester | |
| Base Film Caliper | 4.5 microns | |
| Total Caliper | 6.6 microns +/- 10% | |
| Scanning Capabilities | IR and Visible Light | |
| Regulatory Compliance | | |
| Z-Xtreme [™] 5000T White, Silver, and Clear - UL Recognized 8000T Image Lock [™] Media - UL Recognized | | |
| Product Performance and Suitability | | |
| Recommended storage conditions | 23°F to 104°F (-5°C to 40°C) at 20% to 85% RH | |
| Expected Shelf Life | 1 Year | |
| All products should be pre-tested to ensure it meets all intended | | |

| Weak Chemicals | |
|------------------------|---|
| weak Chemicals | |
| Hexane | Recommended Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |
| Transition Fluid | Test in Your Application |
| Transition Fluid | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | Recommended |
| | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 20001 Label with 5095 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |
| Frains Caslant | Paraman dad |
| Engine Coolant | Recommended Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |
| Windshield Wiper Fluid | Recommended |
| • | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |
| Moderate Chemicals | |
| Denatured Alcohol | Test in Your Application |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | Recommended |
| | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |
| IPA | Recommended |
| | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |
| Harsh Chemicals | |
| Gasoline | Not Recommended |
| | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Test in Your Application |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | Recommended |
| | Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |

| Motor Oil | Test in Your Application |
|-------------------|---|
| motor on | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | Recommended |
| | Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |
| Extreme Chemicals | |
| Acetone | Not Recommended |
| | Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | Test in Your Application |
| | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Recommended |
| | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |
| MEK | Not Recommended |
| MEK | Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | |
| | Test in Your Application |
| | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Recommended |
| | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |
| TCE | Not Recommended |
| | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 4000T Label with 5095 Ribbon |
| | Recommended |
| | Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 5000T Label with Image Lock Ribbon |
| Xylene | Not Recommended |
| • | |
| , | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon |
| | Z-Xtreme 2000T Label with 3200 Ribbon |
| | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon Z-Xtreme 4000T Label with 5095 Ribbon Recommended |
| | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon Z-Xtreme 4000T Label with 5095 Ribbon Recommended Z-Xtreme 4000T Label with 3200 Ribbon |
| | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon Z-Xtreme 4000T Label with 5095 Ribbon Recommended |
| Abrasion Resistar | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon Z-Xtreme 4000T Label with 5095 Ribbon Recommended Z-Xtreme 4000T Label with 3200 Ribbon Z-Xtreme 5000T Label with Image Lock Ribbon |
| | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon Z-Xtreme 4000T Label with 5095 Ribbon Recommended Z-Xtreme 4000T Label with 3200 Ribbon Z-Xtreme 5000T Label with Image Lock Ribbon nce Not Recommended |
| Abrasion Resistar | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon Z-Xtreme 4000T Label with 5095 Ribbon Recommended Z-Xtreme 4000T Label with 3200 Ribbon Z-Xtreme 5000T Label with Image Lock Ribbon Total Not Recommended Z-Xtreme 2000T Label with 3200 Ribbon |
| Abrasion Resistar | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon Z-Xtreme 4000T Label with 5095 Ribbon Recommended Z-Xtreme 4000T Label with 3200 Ribbon Z-Xtreme 5000T Label with Image Lock Ribbon nce Not Recommended |
| Abrasion Resistar | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon Z-Xtreme 4000T Label with 5095 Ribbon Recommended Z-Xtreme 4000T Label with 3200 Ribbon Z-Xtreme 5000T Label with Image Lock Ribbon nce Not Recommended Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 4000T Label with 3200 Ribbon Recommended |
| Abrasion Resistar | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon Z-Xtreme 4000T Label with 5095 Ribbon Recommended Z-Xtreme 4000T Label with 3200 Ribbon Z-Xtreme 5000T Label with Image Lock Ribbon Toce Not Recommended Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 4000T Label with 3200 Ribbon Recommended Z-Xtreme 2000T Label with 5095 Ribbon |
| Abrasion Resistar | Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 2000T Label with 5095 Ribbon Z-Xtreme 4000T Label with 5095 Ribbon Recommended Z-Xtreme 4000T Label with 3200 Ribbon Z-Xtreme 5000T Label with Image Lock Ribbon nce Not Recommended Z-Xtreme 2000T Label with 3200 Ribbon Z-Xtreme 4000T Label with 3200 Ribbon Recommended |

| Not kecommended |
|---|
| Z-Xtreme 2000T Label with 3200 Ribbon |
| Z-Xtreme 4000T Label with 3200 Ribbon |
| |
| Recommended |
| Z-Xtreme 2000T Label with 5095 Ribbon |
| Z-Xtreme 4000T Label with 5095 Ribbon |
| Z-Xtreme 5000T Label with Image Lock Ribbon |
| |
| |

Material Testing in End Application

The information contained in this document is to be used for guidance only and is not intended for use in setting specifications. All purchasers of Zebra products shall be solely responsible for independently determining if the product conforms to all requirements of their unique application.



